



Project Profile Gas Holder



The Problem

The gas holder had been allowed to deteriorate into a very bad condition. There was extensive rusting and after grit blasting, 50-60 holes had appeared in the lower third section.

The Solution

After the entire gas holder had been grit blasted, the inside was coated with one coat of Uni-Tech MC Primer and two coats of Chemi-Tech CR reinforced system.

On the outside, holes were filled with Metal-Tech EG and mesh, then the entire surface was coated with one coat of Corro-Tech GP and two coats of Poly-Nox.

