



Project Profile

Hygienic Floor Protection



The Problem

The client required it's factory floor to be maintained to the same stringent hygiene standards as their production areas.

This involved the application of a hygienic floor coating to the previously untreated concrete floor.

The Solution

The floor was grit blasted to remove any dust and debris.

Areas of porous concrete were primed with Floor-Tech SP Primer and non-porous areas were treated with Uni-Tech GP Primer.

Floor-Tech HB was then applied to the entire surface.

