



Project Profile

Operating Room Refurbishment



The Problem

The internal walls and ceiling of this operating room were in extremely bad condition. A protection system was required that would allow operating procedures to commence as quickly as possible.

The Solution

Uni-Tech GP Primer was applied to both the walls and ceiling. Two coats of Wall-Tech UV in white applied to the ceiling and two coats of Wall-Tech WB in light green applied to the walls. The operating room was able to be put back into service immediately.

