



Profile: Concrete Repair & Protection



The Problem

The project was to completely repair the concrete and coat the surface to provide protection against chemical attack.

The Solution

The damaged concrete was reinstated using **Thortex Floor-Tech RS**. The entire concrete surface was coated with **Thortex Floor-Tech SP Primer**, the metal areas with **Thortex Uni-Tech MC Primer**, over which **Thortex Chemi-Tech CR** was applied.

Our safety surfacing system, **Thortex Grip-Tech**, was used for the edges of the islands.

