



## Project: 54" Pipe Wrap

### The Problem

This WWTP's main in flow pipe – carrying 350 million GPD - had ruptured in several small areas.

RPT and Thortex were called in to affix the repairs during a narrow shutdown window.



### The Solution

RPT applied **Thortex Cerami-Flex EG** at 120 mils over the prepared pipe surfaces. Nylon mesh was imbedded in the wet **Thortex Cerami-Flex EG**. A second coat of **Thortex Cerami-Flex EG** was applied at 60 mils over the meshed surfaces.

A final topcoat of **Thortex Cerami-Flex FG** applied at 40 mils. The finished system was at 240+ mils.

**Thortex America, Inc.**

12 Iron Bridge Drive • Collegeville, PA 19426  
800.578.2772 • [www.thortex.com](http://www.thortex.com)