



## Project: Water Treatment Plant Dam

### The Problem

This water treatment plant had water infiltration through their dam and subsequent erosion of the support fill.



### The Solution

This authority chose RPT and Thortex to replace over 1100 linear feet of joint with **Thortex Flexi-Tech 80 EG**.

**Thortex Flexi-Tech 80 EG** is a solvent-free, paste-grade elastomer that is applied by trowel or putty knife and possess outstanding mechanical strength when cured.