



Profile: Furnace Exhaust Gas Ventilator Refurbishment



The Problem

The housing, impeller and castings of this furnace exhaust gas ventilator had been marked for refurbishment.

The client required a high temperature resistant coating.

The Solution

The internal components were abrasive blast cleaned to ensure all loose abrasive dust and debris were cleaned away and then **Thortex Cerami-Tech HTX** was applied.

Thortex Cerami-Tech HTX is a high-performance, fluid-grade engineering resurfacing compound developed for high temperature immersion conditions and is ideal for resurfacing pumps, impellers, valves, tube sheets, water boxes and heat exchangers.

