



## Project Profile

# Shower Block Floor Refurbishment



### The Problem

The floor was in poor condition and was becoming unhygienic. The client wanted a high performance coating system which would provide a high performance solution to the problem.

### The Solution

The entire floor was primed with Floor-Tech SP Primer prior to the application of two coats of Floor-Tech WB, which incorporated Floor-Tech WB Aggregate to provide the required slip-deterrent finish.

